

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: AC power cable removed for testing.



Report Number: SAR.20190516



Test Position Front 0 mm Gap

Note: AC power cable removed for testing.



Report Number: SAR.20190516



Front of Device



Report Number: SAR.20190516



Back of Device