
Photos from test of Smart Box Link, 200612

Project no.: 618-20125

Photos from test report 618-20125-10-R2

31 August 2018

**DELTA Development
Technology AB**
Finnslätten
Elektronikgatan 47
721 36 Västerås
Sweden

Tel. 021-31 44 80
info@delta-dt.se
www.delta-dt.se

Bankgiro 5534-7728
VAT SE 556556207001

DELTA Development
Technology AB
is a subsidiary company of
DELTA

1. External photos of test object



Photo 1.1 Test object.



Photo 1.2 Test object.




Photo 1.3 Photo taken on client document showing label intended to be placed on test object.

2. Test set up photos



Photo 2.1 Test set up regarding measurement of radio frequency electromagnetic field below 1 GHz.



Photo 2.2 Test set up regarding measurement of radio frequency electromagnetic field below 1 GHz




Photo 2.3 Test set up regarding measurement of radio frequency electromagnetic field below 1 GHz. Horizontal orientation



Photo 2.4 Test set up regarding measurement of radio frequency electromagnetic field below 1 GHz. Horizontal orientation




Photo 2.5 Test set up regarding measurement of radio frequency electromagnetic field above 1 GHz.



Photo 2.6 Test set up regarding measurement of radio frequency electromagnetic field above 1 GHz




Photo 2.7 Test set up regarding measurement of radio frequency electromagnetic field above 1 GHz. Horizontal orientation



Photo 2.8 Test set up regarding measurement of radio frequency electromagnetic field above 1 GHz. Horizontal orientation



Photo 2.9 Test set up regarding radio parameter tests in chapter 4.3, 4.6 and 4.7 in test report.



Photo 2.10 Test set up regarding radio parameter tests in chapter 4.3, 4.6 and 4.7 in test report.



Photo 2.11 Test set up regarding radio parameter tests in chapter 4.4 and 4.5 in test report.