SAR TEST REPORT Report No. :FA1D1704

Appendix D. SAR Test Setup Photos

Head Exposure Condition





Front at 10 mm

Bottom Side at 10 mm

Body-worn Exposure Condition







Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm

TEL: 886-3-327-3456 Page: D1 of D3
FAX: 886-3-328-4978 Issued Date: Apr. 07, 2022

Template version: 211220












Top Side at 0 mm

Bottom Side at 0 mm



Front with Clip at 0 mm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Template version: 211220 Page: D2 of D3 Issued Date: Apr. 07, 2022











Front at 0 mm

Back at 0 mm





Right Side at 0 mm

Left Side at 0 mm





Top Side at 0 mm

Bottom Side at 0 mm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Template version: 211220 Page: D3 of D3 Issued Date: Apr. 07, 2022