



APPENDIX 3: Photographs of test setup


Radiated Spurious Emission



Rear (Below 1 GHz)




Rear (Above 1 GHz)



Worst Case Position


X-axis



Y-axis



Z-axis



End of Report