








Report No.: EED32M00138904

Page 435 of 438

PHOTOGRAPHS OF TEST SETUP

Test mode No:GP15A



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)










Report No.: EED32M00138904

Page 436 of 438



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup There are absorbing materials under the ground.



















Report No.: EED32M00138904

Page 437 of 438



Radiated spurious emission Test Setup-5(Above 18GHz)



Conducted Emissions



















Report No. : EED32M00138904 Page 438 of 438

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32M00138901 for EUT external and internal photos.



The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.





