



Test Report	18070903
Page	4 of 6

## **EUT Internal Photo**

Cover Off - Top View




Mainboard - Front View






Test Report	18070903
Page	5 of 6

Mainboard - Rear View



Battery - Front View





Test Report	18070903
Page	6 of 6

Battery - Rear View



Antenna View

