

Report No. : EED32O80625201




Page 33 of 46

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: DET-3019b



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Hotline:400-6788-333 www.cti-cert.com E-mail:info@cti-cert.com Complaint call:0755-33681700 Complaint E-mail:complaint@cti-cert.com




Report No. : EED32O80625201









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

