

Report No. : EED32O80866201



Page 37 of 52

8 PHOTOGRAPHS OF TEST SETUP

Test model No.: DBP-6293L



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)





Report No. : EED32O80866201









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



CONDUCTED EMISSION TEST SETUP















