

Report No. : EED32O81897501



9 PHOTOGRAPHS OF TEST SETUP

Test model No.: DBP-62A2B



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)








Report No. : EED32O81897501









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

