

Report No. : EED32O81897601

Page 37 of 49

## **9 PHOTOGRAPHS OF TEST SETUP**

Test model No.: DBP-62A4B



Radiated spurious emission Test Setup-1(Below 1GHz)





Report No. : EED32O81897601









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 











