



Report No. : EED32P81026801



9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)




Radiated spurious emission Test Setup-2(Above 1GHz)



Report No. : EED32P81026801









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

