


Report No.: EED32P82069601 Page 36 of 49

## 9 PHOTOGRAPHS OF TEST SETUP



**RF test system Test Setup** 



Radiated spurious emission Test Setup-1(Below 1GHz)














Report No.: EED32P82069601 Page 37 of 49



Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

















