

## Internal Photos of the EUT



Fig. 1





Fig. 2





Fig. 3



115.1







Fig. 5



*This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 6* 







Fig. 7



*This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 6* 







Fig. 9



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 6





Fig. 11




Fig. 12