
SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ARRH-SC-100

Report No.:LCS180927046AEB


1.1.Photograph of liquid depth



Photograph of the depth in the Body Phantom (2450MHz, 15.1cm depth)


SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ARRH-SC-100 Report No.:LCS180927046AEB

1.2.Photograph of the Test



0mm body-worn Back Side Setup Photo


0mm body-worn Front Side Setup Photo



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 2 of 5

SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ARRH-SC-100 Report No.:LCS180927046AEB

0mm body-worn Top Side Setup Photo



0mm body-worn Left Side Setup Photo



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 5 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ARRH-SC-100 Report No.:LCS180927046AEB

0mm body-worn Right Side Setup Photo



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 5

Report No.:LCS180927046AEB

1.3.EUT Photographs





Fig.1



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 5