


Report No.: EED32N80725101

7 PHOTOGRAPHS OF TEST SETUP

Test model No.:L36



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N80725101



Radiated spurious emission Test Setup-5(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission









