


Report No. : EED32O80708601




7 PHOTOGRAPHS OF TEST SETUP

Test model No.: M906



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-1(Below 1GHz)








Report No. : EED32O80708601






Page 31 of 37



Radiated spurious emission Test Setup-2(1-18 GHz)



There are absorbing materials under the ground.









