

Report No. : EED32O80105501




Page 28 of 47

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: MINISO-P66



Radiated spurious emission Test Setup-1 left ear(Below 1GHz)







Page 29 of 47



CTI华测检测



Radiated spurious emission Test Setup-1 right ear(Below 1GHz)



Radiated spurious emission Test Setup-2 right ear(Above 1GHz)




Report No. : EED32O80105501





Page 30 of 47



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

