



Report No.: EED32O80444201 Page 48 of 69

## 7 PHOTOGRAPHS OF TEST SETUP





Radiated spurious emission Test Setup-1 left ear(Below 1GHz)




Radiated spurious emission Test Setup-2 left ear(Above 1GHz)




Report No.: EED32O80444201





Radiated spurious emission Test Setup-1 right ear(Below 1GHz)



Radiated spurious emission Test Setup-2 right ear(Above 1GHz)














Report No.: EED32O80444201





Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.

