



Report No. : EED32N80339001 Page 38 of 47

## **8 PHOTOGRAPHS OF TEST SETUP**

Test model No.: TM-053



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com







Page 39 of 47



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.













































