


Report No.: EED32O81632401 Page 35 of 51

10PHOTOGRAPHS OF EUT Constructional Details

Test Model No.:TS37



View of Product-1



View of Product-2















Page 36 of 51 Report No.: EED32O81632401



View of Product-3



View of Product-4














Report No.: EED32O81632401 Page 37 of 51



View of Product-5



View of Product-6













Page 38 of 51 Report No.: EED32O81632401



View of Product-7



View of Product-8













Page 39 of 51 Report No.: EED32O81632401



View of Product-9



View of Product-10













Page 40 of 51 Report No.: EED32O81632401



View of Product-11 Ear L



View of Product-12 Ear L














Page 41 of 51 Report No.: EED32O81632401



View of Product-13 Ear L



View of Product-14 Ear L













Report No.: EED32O81632401 Page 42 of 51



View of Product-15 Ear L



View of Product-16 Ear L









