



Report No. : EED32O81632401 Page 32 of 51

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: TS37




Radiated spurious emission Test Setup-1 left ear(Below 1GHz)



Radiated spurious emission Test Setup-2 left ear(Above 1GHz)



Report No.: EED32O81632401 Page 33 of 51



Radiated spurious emission Test Setup-1 right ear(Below 1GHz)



Radiated spurious emission Test Setup-2 right ear(Above 1GHz)













Report No.: EED32O81632401 Page 34 of 51



