



Test Report	Q181127S005
Page	4 of 7

EUT Internal Photo







Cover off view 2



Test Report	Q181127S005
Page	5 of 7

PCB - Front View







uu



Test Report	Q181127S005
Page	6 of 7

Battery - Front View







Test Report	Q181127S005
Page	7 of 7

Antenna View

