

3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0488 Page (23) of (27)

# **APPENDIX B - Test Setup Photos and Configuration**

### **Conducted Emissions at Mains Power Ports**

■ AC 120 V, 60 Hz\_Charging







3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0488 Page (24) of (27)

## Radiated Electric Field Emissions(Below 1 6 ₪)

■ AC 120 V, 60 Hz\_Charging








3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0488 Page (25) of (27)

■ Battery\_Operating









3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0488 Page (26) of (27)

# Radiated Electric Field Emissions(Above 1 6 ₪2)

■ AC 120 V, 60 Hz\_Charging







3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-EM-22T0488 Page (27) of (27)

■ Battery\_Operating

