



5 TEST CONDITIONS AND RESULTS

5.1 EBW and OBW


For test instruments and accessories used see section 6 Part MB.

5.1.1 Description of the test location

Test location: Anechoic chamber 1

5.1.2 Photo documentation of the test set-up







CSA Group Bayern GmbH Ohmstrasse 1-4 · 94342 STRASSKIRCHEN · GERMANY Tel.:+49(0)9424-94810 · Fax:+49(0)9424-9481440 File No. T47140-01-00LH, page 12 of 44

Rev. No. 6.3 2021-02-08