



Report No.: EED32O80874101 Page 37 of 51

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: GZ30



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz)



Report No.: EED32O80874101 Page 38 of 51



Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.













Report No.: EED32O80874101 Page 39 of 51



Conducted Emissions Test Setup(adapter 1)



Conducted Emissions Test Setup(adapter 2)

