


Report No.: EED32O80493201 Page 39 of 59

## 9 PHOTOGRAPHS OF TEST SETUP

Test model No.: QTZEG1N




Radiated spurious emission Test Setup-1(Below 1GHz)




Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80493201 Page 40 of 59



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup(adapter 1)** 



















Report No.: EED32O80493201

