


Report No. : EED32P80349001 Page 32 of 57

9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1 left ear(Below 1GHz)



Radiated spurious emission Test Setup-2 left ear(Above 1GHz)



Page 33 of 57 Report No.: EED32P80349001



Radiated spurious emission Test Setup-1 right ear(Below 1GHz)



Radiated spurious emission Test Setup-2 right ear(Above 1GHz)













Report No.: EED32P80349001 Page 34 of 57

