

Fig.1




Fig.2

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 1 of 5

Internal Photos of the EUT




Fig.3




Fig.4

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 2 of 5




Fig.5




Fig.6

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 5 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.




Fig.7




Fig.8

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 5 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.




Fig.9

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 5