

Report No. : EED32M00031201




Page 41 of 48



PHOTOGRAPHS OF TEST SETUP

Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)












Page 42 of 48



Radiated spurious emission Test Setup-3(Above 1GHz)





Report No. : EED32M00031201



Page 43 of 48



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup

