



Report No. :EED32N81223701 Page 36 of 58

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: MAXLITEA



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No. :EED32N81223701





Conducted emission Test Setup



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.









