

Report No. : EED32O81465501



Page 36 of 55

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: MD-150



Radiated spurious emission Test Setup-1(Below 1GHz)





Report No. : EED32O81465501





Page 37 of 55



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



