


Report No. : EED32O81465503 Page 56 of 58

## 9 PHOTOGRAPHS OF TEST SETUP

Test model No.: MD-150




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O81465503 Page 57 of 58



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 













Report No. : EED32O81465503 Page 58 of 58

## 10 PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32O81465501 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

