## APPENDIX E: PHOTOGRAPHS OF THE TEST SET-UP

Report No.: WT228002146 Page 1 of 6

Photo 1: Measurement DASY6








Photo 5: Right Tilt





Photo 4: Right Cheek




Photo 6: Front Side 15mm

Report No.: WT228002146 Page 2 of 6



Photo 7: Back Side 15mm



Photo 8: Front Side 10mm



Photo 9: Back Side 10mm



Photo 10: Left Side 10mm





Report No.: WT228002146 Page 3 of 6

## Photo 11: Right Side 10mm



Photo 12: Top Side 10mm



Photo 13: Bottom Side 10mm



1

Page 4 of 6

Report No.: WT228002146

## Photograph: Liquid depth

Photo 18: Head 750 Depth (15.0cm)




Photo 20: Head 1900 Depth (15.0cm)



Photo 22: Head 1750 Depth (15.0cm)

Photo 19: Head 835 Depth (15.0cm)



Photo 21: Head 2450 Depth (15.0cm)



Photo 23: Head 2600 Depth (15.0cm)

Report No.: WT228002146 Page 5 of 6





Report No.: WT228002146 Page 6 of 6