



Report No.: EED32Q80175801 Page 29 of 38

8 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Page 30 of 38 Report No.: EED32Q80175801



