



Page 48 of 51

PHOTOGRAPHS OF TEST SETUP

Test mode No:N901



Radiated spurious emission Test Setup-1(Below 30MHz)











Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4 There are absorbing materials under the ground.

















PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32M00160901 for EUT external and internal photos.

