


Report No. : EED32N80153706 Page 26 of 29

DFS TEST SETUP

Test model No.:HP23ATQC



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)



Page 27 of 29 Report No.: EED32N80153706



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.














Page 28 of 29 Report No.: EED32N80153706



Radiated spurious emission Test Setup-5(Above 18GHz)



Conducted Emissions Test Setup



















Report No.: EED32N80153706

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32N80153701 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

