


Report No. : EED32M00052603 Page 199 of 202

PHOTOGRAPHS OF TEST SETUP

Test model No:PP23TQB



Radiated spurious emission Test Setup-1 (Below 30M)



Radiated spurious emission Test Setup-2 (Below 1GHz)

Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com



Page 200 of 202 Report No.: EED32M00052603



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.





















AC Conducted Emissions Test Setup











