


Report No.: EED32O80418001 Page 34 of 42

7 PHOTOGRAPHS OF TEST SETUP

Test model No.: PPCC01




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80418001





Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.

