








Report No. : EED32M00266502 Page 106 of 109




## PHOTOGRAPHS OF TEST SETUP

Test model No.:SPD10



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)





















Report No. : EED32M00266502 Page 107 of 109



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.



















Report No.: EED32M00266502

Page 108 of 109



































































Report No. : EED32M00266502 Page 109 of 109

## **PHOTOGRAPHS OF EUT Constructional Details**

Refer to Report No. EED32M00266501 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

