




PHOTOGRAPHS OF TEST SETUP

Test model No.:SPD10




Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)



Report No. : EED32M00266503 Page 90 of 92



Radiated spurious emission Test Setup-3(Above 1GHz)

















Report No.: EED32M00266503







Radiated spurious emission Test Setup-5(Above 1GHz)
There are absorbing materials under the ground.



Conducted Emissions Test Setup













Report No. : EED32M00266503 Page 92 of 92

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32M00266501 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

