



Report No.: EED32N80136902 Page 44 of 45

## PHOTOGRAPHS OF TEST SETUP

Test Model No.: CONNECT



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com









## **PHOTOGRAPHS OF EUT Constructional Details**

Refer to Report No. EED32N80136901 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

