




9 PHOTOGRAPHS OF TEST SETUP

Test model No.: iSmartEV P03




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Page 33 of 52 Report No.: EED32O81503001



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup









