

Report No. : EED32O81503003 Page 46 of 48

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: iSmartEV P03




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O81503003 Page 47 of 48



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup













Report No. : EED32O81503003 Page 48 of 48

10 PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32O81503001 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

*** End of Report ***

