



PHOTOGRAPHS OF TEST SETUP

Test model No.:iSmartEV P03



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32O81503006 Page 55 of 57



Radiated spurious emission Test Setup-3(Above 18GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.




















Report No.: EED32O81503006



































Report No.: EED32O81503006

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32O81503001 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

