





PHOTOGRAPHS OF TEST SETUP

Test model No.: iSmartTool 601Max



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Page 43 of 45 Report No. :EED32N80831503



Radiated spurious emission Test Setup-3(Above 18GHz)



Conducted Emissions Test Setup















Report No. :EED32N80831503











Report No. :EED32N80831503 Page 45 of 45

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32N80831501 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

