


Report No. : EED32Q80276402 Page 40 of 44

PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz)







Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)














Page 42 of 44 Report No. : EED32Q80276402



Radiated spurious emission Test Setup-5(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup-1

















Report No.: EED32Q80276402

Page 43 of 44



Conducted Emissions Test Setup-2





















































