



Report No. : EED32O80475701 Page 37 of 50

8 PHOTOGRAPHS OF TEST SETUP

Test model No.:S1132HB




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80475701 Page 38 of 50



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup









