






PHOTOGRAPHS OF TEST SETUP

Test Model No.: S9246AA



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32O81615901 Page 38 of 48



Radiated spurious emission Test Setup-3Above 1GHz)
There are absorbing materials under the ground.



AC Power Line Conducted Emission









