


Report No.: EED32O81362701 Page 32 of 40

## 9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1: (Below 1GHz)



Radiated spurious emission Test Setup-2: (Below 1GHz)Close up photo














Report No.: EED32O81362701 Page 33 of 40



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)Close up photo

















Radiated spurious emission Test Setup-5(Above 1GHz)
There are absorbing materials under the ground.

