


Report No. : EED32O81133401 Page 33 of 40

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: SKGBLEXK01



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O81133401 Page 34 of 40

